

# Annexure D

## BUILDING SAFETY CERTIFICATE

No.

Dated: .....

It is certified that the existing building Aryaman Vikram Birla Inst. of Learning (name of the building or premises) at Raja Rani Vihar, Haldwani (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+1+1	G+1+1	G+1+1	—	—	—

The building is owned/occupied by AVBIL Haldwani (name of the Institution) have complied with the Building safety requirements in accordance with National Building code.Rules, and verified by the officers concerned of C.D.P.W.D. Haldwani (Name of Department/ Govt.) on 02/05/2024 (date of inspection) in the presence of Shri P.J.S. Cheema, Drc. AVBIL (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 03/05/2024 for a period of TWO years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 02/05/2024 at Haldwani by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : Executive Engineer  
CD PWD Haldwani

Name : Ashok Kumar

Designation : Executive Engineer

Name & Address of Department/ Office: CD PWD  
Haldwani